

Community Advisory Group Meeting #4a  
June 25, 2014  
Locations of Photo Simulation Key Observation Points  
Note: Photos taken during spring 2014







Existing Conditions



Conceptual Project

Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/9/2014

Address	136th Ave NE
Date	4/9/2014
Time	1:08 PM
Viewing Direction	North
Structure	G2-5 Short Span

# KOP CENTRAL 2 SEGMENT E





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/9/2014

Address	136th Ave NE
Date	4/9/2014
Time	1:08 PM
Viewing Direction	North
Structure	G2-5 Long Span

# KOP CENTRAL 2 SEGMENT E





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review 4/2/2014

Address	13600 SE 5th St
Date	4/2/2014
Time	2:54 PM
Viewing Direction	North
Structure	G2-1, G2-5

# KOP CENTRAL 3 SEGMENT E





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review 4/2/2014


Address	13600 SE 5th St
Date	4/2/2014
Time	2:54 PM
Viewing Direction	North
Structure	G2-5

# KOP CENTRAL 3 SEGMENT E





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/2/2014


Address	13711 SE 18th St
Date	4/2/2014
Time	3:19 PM
Viewing Direction	West
Structure	G2-1

# KOP CENTRAL 4 SEGMENT E





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/2/2014

Address	13711 SE 18th St
Date	4/2/2014
Time	3:19 PM
Viewing Direction	West
Structure	G2-5

# KOP CENTRAL 4 SEGMENT E





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

3/31/2014

Address	2160 135th PI SE
Date	3/31/2014
Time	4:00 PM
Viewing Direction	Southeast
Structure Type	G2-1

# KOP CENTRAL 5 SEGMENT E, J





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

3/31/2014

Address	2160 135th PI SE
Date	3/31/2014
Time	4:00 PM
Viewing Direction	Southeast
Structure Type:	G2-5

# KOP CENTRAL 5 SEGMENT E, J





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review 5/7/2014

Address	4122 Factoria Blvd SE
Date	5/7/2014
Time	12:24 PM
Viewing Direction	North
Structure	G2-6

# KOP CENTRAL 12 SEGMENT I







Address	4122 Factoria Blvd SE
Date	5/7/2014
Time	12:24 PM
Viewing Direction	North
Structure	G2-6

# KOP CENTRAL 12 SEGMENT I





Existing Conditions



Conceptual Project




Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/10/2014


Address	4489 137th Ave SE
Date	4/10/2014
Time	9:32 AM
Viewing Direction	North
Structure Type	G2-9

# KOP CENTRAL 15 SEGMENT J





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/10/2014

Address	4489 137th Ave SE
Date	4/10/2014
Time	9:32 AM
Viewing Direction	North
Structure Type:	G2-10

# KOP CENTRAL 15 SEGMENT J





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/1/2014

Address	4620 136th Ave SE
Date	4/1/2014
Time	9:49 AM
Viewing Direction	West
Structure Type	G2-10

# KOP CENTRAL 16 SEGMENT J






Existing Conditions

# KOP CENTRAL 18 SEGMENT J

Address	4411 137th Ave SE
Date	5/7/2014
Time	10:53 AM
Viewing Direction	Northwest
Structure	G2-9



Conceptual Project

Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

5/7/2014



energizeEASTSIDE








Existing Conditions

# KOP CENTRAL 18 SEGMENT J

Address	4411 137th Ave SE
Date	5/7/2014
Time	10:53 AM
Viewing Direction	Northwest
Structure	G2-10



Conceptual Project

Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

5/7/2014



energizeEASTSIDE






# KOP CENTRAL 19 SEGMENT H

Address	4077 120th Ave SE
Date	5/7/2014
Time	3:49 PM
Viewing Direction	West
Structure	G4-3 (In view)



Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

5/7/2014

energizeEASTSIDE

PSE PUGET SOUND ENERGY




# KOP CENTRAL 19 SEGMENT H

Address	4077 120th Ave SE
Date	5/7/2014
Time	3:49 PM
Viewing Direction	West
Structure	G4-3 (Not in view)



Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

5/7/2014

energizeEASTSIDE

PSE PUGET SOUND ENERGY