

Community Advisory Group Meeting #4a  
June 25, 2014  
Locations of Photo Simulation Key Observation Points  
Note: Photos taken during spring 2014







Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

3/31/2014

Address	13615 NE 78th PI
Date	3/31/2014
Time	11:20 AM
Viewing Direction	West
Structure	G2-1

# KOP NORTH 1 SEGMENT C





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

3/31/2014

Address	13538 NE 54th PI
Date	3/31/2014
Time	10:49 AM
Viewing Direction	North
Structure	G2-5

# KOP NORTH 3 SEGMENT C





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

3/31/2014

Address	13538 NE 54th PI
Date	3/31/2014
Time	10:49 AM
Viewing Direction	North
Structure	G2-6

# KOP NORTH 3 SEGMENT C





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/2/2014

Address	12596 Bel-Red Rd
Date	4/2/2014
Time	9:44 AM
Viewing Direction	East
Structure	G3-2

# KOP NORTH 5 SEGMENT D





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/2/2014

Address	12596 Bel-Red Rd
Date	4/2/2014
Time	9:44 AM
Viewing Direction	East
Structure	G3-4

# KOP NORTH 5 SEGMENT D





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/9/2014


Address	293 116th Ave NE
Date	4/9/2014
Time	2:42 PM
Viewing Direction	East
Structure	G4-5

# KOP NORTH 6 SEGMENT B





Existing Conditions



Conceptual Project

POWER ENGINEERS

4/9/2014


Address	4630 116th Ave NE
Date	4/9/2014
Time	2:00 PM
Viewing Direction	North
Structure	G3-4

# KOP NORTH 9 SEGMENT B





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

4/9/2014

Address	4630 116th Ave NE
Date	4/9/2014
Time	2:00 PM
Viewing Direction	North
Structure	G3-8

# KOP NORTH 9 SEGMENT B





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

3/31/2014

Address	12056 NE 70th St
Date	3/31/2014
Time	1:05 PM
Viewing Direction	West
Structure	G3-2

# KOP NORTH 10 SEGMENT B





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

3/31/2014

Address	12056 NE 70th St
Date	3/31/2014
Time	1:05 PM
Viewing Direction	West
Structure	G3-4

# KOP NORTH 10 SEGMENT B





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

5/8/2014

Address	11600 NE 60 St
Date	5/8/2014
Time	4:36 PM
Viewing Direction	South
Structure	G3-4

# KOP NORTH 13 SEGMENT B





Existing Conditions



Conceptual Project



Photo simulations are for discussion purposes only and may change pending public, regulatory and utility review

5/8/2014

Address	11600 NE 60 St
Date	5/8/2014
Time	4:36 PM
Viewing Direction	South
Structure	G3-8

# KOP NORTH 13 SEGMENT B