


EVALUATION FACTOR:

Protects mature vegetation



Mature vegetation includes the total number of trees* that would require removal or trimming if the potential route option was constructed.

ROUTE OPTIONS RECOMMENDED for further evaluation by the Community Advisory Group

Data	Unit	Min	Max	Ash	Aspen	Cedar	Cottonwood	Elm	Laurel	Oak	Pine	Redwood	Sycamore	Willow
Tree Removal	Trees	7,756	9,706	8,084	9,049	9,566	8,699	9,125	9,706	7,756	8,560	8,985	9,175	7,879

ROUTE OPTIONS NOT RECOMMENDED for further evaluation by the Community Advisory Group

Data	Unit	Min	Max	Cherry	Dogwood	Fir	Magnolia	Maple	Poplar	Spruce
Tree Removal	Trees	9,377	12,374	9,853	11,898	11,078	9,377	10,182	12,374	9,601

*Tree counts indicated are those greater than 4 inches in diameter at breast height (dbh)